

INFORMATION REPORT INFORMATION REPORT**CENTRAL INTELLIGENCE AGENCY**

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

C-O-N-F-I-D-E-N-T-I-A-L

25X1

COUNTRY **Czechoslovakia**
SUBJECT **Road Data/Bridges**

REPORT

DATE DISTR.

NO. PAGES **2**

REFERENCES

25X1

DATE OF
INFO.
PLACE &
DATE ACQ

25X1

THIS IS UNEVALUATED INFORMATION

2. [] route was from Bratislava to Trencin via Trnava. The road [] is considered to be a first class highway in Czechoslovakia. It is an all surface, all weather road [] which is over two lanes wide and is in good condition. The road has a good solid foundation and is asphalt surfaced. 25X1
3. The curves of the road are shallow [] was able to attain fairly high speeds on the road. The road runs through shallow rolling hills and is fairly well maintained. The road is designed for heavy usage and is crowned for easy drainage. [] many heavy military Shoda trucks but [] the trucks were tarpaulin covered. [] very few civilian cars on the road. [] did not see any military installations, airfields or factories along this route, just farms and woodlands. 25X1
4. [] between Bratislava and Trencin [] approximately eight highway bridges. [] dared not take any pictures of any bridges for fear of being reported and getting into trouble. The first bridge is located in Piestany. It is a concrete bridge reinforced with steel and is approximately two lanes wide. The bridge crosses the Dubova river which flows from the northwest to the southeast and into the Vah River which flows from the north southward. The bridge is in good condition and is able to absorb heavy usage. 25X1

5
4
3
2
1**C-O-N-F-I-D-E-N-T-I-A-L**5
4
3
2
1

STATE	ARMY	NAVY	AIR	FBI	AEC						
-------	------	------	-----	-----	-----	--	--	--	--	--	--

INFORMATION REPORT INFORMATION REPORT**NOFORN****NO DISSEM ABROAD****LIMITED**

LIMITED: Dissemination limited to full-time employees of CIA, AEC and FBI; and, within State and Defense, to the intelligence components, other offices producing NIS elements, and higher echelons with their immediate supporting staffs. Not to be disseminated to consultants, external projects or reserve personnel on short term active duty (excepting individuals who are normally full-time employees of CIA, AEC, FBI, State or Defense) unless the written permission of the originating office has been obtained through the Assistant Director for Central Reference, CIA.

25X1

C-O-N-F-I-D-E-N-T-I-A-L

-2-

5. The second concrete-steel reinforced bridge is located in Ishice. This bridge is over two lanes wide and is in good condition. It crosses the Klamessian river which also flows from the northwest to the southeast and into the Vah River. The bridge is constructed for heavy usage. The third and fourth bridges are located near Truno-Bokmalavice. Both bridges cross the Bzenova river which flows down from the northwest to the southeast into the Vah River. Both are of concrete construction. However, both were two lanes wide and constructed for heavy usage. 25X1
6. The fifth bridge is located at Ivanovec and the sixth bridge is located at Velcice. Both are concrete-steel reinforced bridges. They are approximately two lanes wide, in good condition and are able to absorb heavy usage. The bridge at Ivanovec crosses the Ivanovicky river which flows down from the mountains located northwest of Ivanovec and flows southeast into the Vah River. The sixth bridge at Velcice crosses the Chochalsian river which also flows down from the mountains in the northwest and in a southeasterly direction, into the Vah River.
7. The seventh bridge is located in Kostolac. It is a concrete-steel reinforced bridge which is over two lanes wide, in good condition and is also able to absorb heavy military traffic. The bridge crosses the Brielanacian river which flows down from the north in a southerly direction into the Vah River. The eighth concrete-steel reinforced bridge is located in Trnava. The bridge crosses the Vah River which flows from the northeast in a southwesterly direction and eventually joins the Danube River. The bridge is approximately three lanes wide, is in good condition and is able to absorb heavy usage. 25X1

-end-

C-O-N-F-I-D-E-N-T-I-A-L

NOFORN

NO DISSEM ABROAD

LIMITED



